

CUSTOMER-OWNED PIPE INVENTORY SPREADSHEET									
Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified	If "YES" Service Line was Field Verified		Parcel Number	Notes	
					Describe Verification Method	Date			
Lead Lead-Lined Galvanized Galvanized Non-Lead Copper Non-Lead Plastic Non-Lead Other Unknown-Likely Lead Unknown-Unlikely Lead Unknown-Material Unknown	Date, Year or estimated date range service line was installed or replaced	Pipe Diameter in Inches	Previous Material Evaluation Installation Record Installation date after lead ban Service Line diameter is > 2 inches Service Line repair/replacement record Predictive Model Water sampling only w/no records Field Inspection only w/no records		Customer Self-Identification Water Quality Sampling Mechanical Excavation at one location Mechanical Excavation at multiple locations. Visual Inspection at Meter Pit Scrape/Magnet Test				
275 Kai Road, Freeland Washington, 98249	1988		Installation date after lead ban						
4920 Scurlock Road, Freeland Washington, 98249	1996		Installation date after lead ban						
287 Fairhaven Drive, Freeland Washington, 98249	1996		Installation date after lead ban						
4924 Scurlock Road, Freeland Washington, 98249	1999		Installation date after lead ban						
271 Kai Road, Freeland Washington, 98249	2004		Installation date after lead ban						
260 Kai Road, Freeland Washington, 98249	2005		Installation date after lead ban						
4903 Magellan Street, Freeland Washington, 98249	2007		Installation date after lead ban						
4894 Thistle Lane, Freeland Washington, 98249	2013		Installation date after lead ban						
4883 Magellan Street, Freeland Washington, 98249	2015		Installation date after lead ban						
<b>2024 - SERVICE LINE MATERIAL NEEDING VERIFICATION in HOMES BUILT BEFORE 1986 LEAD BAN LEGISLATION IN WASHINGTON STATE</b>							<b>PARCEL NUMBER</b>	<b>NOTES</b>	
4885 Magellan Street, Freeland Washington, 98249	Non-Lead Plastic	2003	1" O.D.	Service Line repair/replacement record	No			029-S6205-00-08014-0	Installation Record
4914 Scurlock Road, Freeland Washington, 98249	Non-Lead Plastic	2000-2004	1" O.D.	Service Line repair/replacement record	No			029-S6205-00-07004-0	Customer Self-Identified
267 Fairhaven Drive, Freeland Washington, 98249	Non-Lead Plastic	74 - 76	1" O.D.	Field Inspection only w/no records	Yes	Visual Inspection at Meter Pit	4/24/2024	029-S6205-00-07005-0	
267 Kai Road, Freeland Washington, 98249	Non-Lead - Plastic	2000-2001	1" O.D.	Service Line repair/replacement record	Yes	Visual Inspection at Meter Pit	4/14/2024	029-S6205-00-08012-0	Line replaced after fire destroyed original home
295 Fairhaven Drive, Freeland Washington, 98249	Non-Lead - Plastic	1986 > 87	1" O.D.	Service Line repair/replacement record	Yes	Visual Inspection at Meter Pit	4/24/2024	029-S6205-00-07001-0	Additional Inspection at Secondary Access Point
4925 Magellan Street, Freeland Washington, 98249	Non-Lead Plastic	1974	1" O.D.	Field Inspection only w/no records	Yes	Visual Inspection at Meter Pit	4/24/2024	029-S6205-00-07010-0	
4901 Thistle Lane, Freeland Washington, 98249	Non-Lead Plastic	1974	1" O.D.	Service Line diameter is > 2 inches	Yes	Visual Inspection at Meter Pit	4/24/2024	029-S6205-00-08009-0	
4936 Thistle Lane, Freeland Washington, 98249	Non-Lead Plastic	2023 > 24	1" O.D.	Service Line repair/replacement record	Yes	Visual Inspection at Meter Pit	4/24/2024	029-S6205-00-07011-0	Remodel/Installation
4886 Thistle Lane, Freeland Washington, 98249	Non-Lead Copper	2003	1" O.D.	Service Line repair/replacement record	No			029-S6205-00-08015-0	Installation Record
4909 Thistle Lane, Freeland Washington, 98249	Galvanized	1978	1" O.D.	Field Inspection only w/no records	Yes	Scrape/Magnet Test	3/31/2024	029-S6205-00-08007-0	Visual Inspection at Secondary Access Point
4886 Scurlock Road, Freeland Washington, 98249	Non-Lead Plastic	1979	1" O.D.	Service Line diameter is > 2 inches	No			029-S6205-00-08016-0	Customer Self-Identified
4921 Thistle Lane, Freeland Washington, 98249	Non-Lead - Plastic	1979	1" O.D.	Installation Record	Yes	Visual Inspection at Meter Pit	4/14/2024	029-S6205-00-07006-0	Additional Inspection at Secondary Access Point
4902 Thistle Lane, Freeland Washington, 98249	Non-Lead - Plastic	1983	1" O.D.	Field Inspection only w/no records	Yes	Visual Inspection at Meter Pit	4/1/2024	029-S6205-00-08002-0	
4899 Thistle Lane, Freeland Washington, 98249	Non-Lead - Plastic	1984	1" O.D.	Field Inspection only w/no records	Yes	Visual Inspection at Meter Pit	4/20/2024	029-S6205-00-08100-0	Visual Inspection at Secondary Access Point
4940 Thistle Lane, Freeland Washington, 98249	Non-Lead - Plastic	1984	1" O.D.	Field Inspection only w/no records	Yes	Visual Inspection at Meter Pit	4/24/2024	029-S6205-00-07012-0	